

VEHICLE INSPECTION REPORT

PJ20ZFV

Mercedes-Benz Sprinter 314 CDI

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Present

Details

Reg. date 07/08/2020

Year 2020

Mileage 173,701 Miles
Warranted

Fuel Type Diesel

Colour WHITE

VIN W1V9076352P254360

Body Style Panel Van L3

MOT Due 06/08/2026

CAP Clean £7,725.00

CAP Average £6,775.00

CAP Below £5,425.00

Gearbox AUTOMATIC

Gears 6

AD BLUE, SIDE LOADING DOOR

Tyres

NSF

NSR

OSF

OSR


Spare

Features


- Rear parking sensor
- Front electric windows

Photos






Condition Check





Damage Photos




1: Wing osf
Scratched
Over 25mm Not Thru Paint


2: Bumper Front Moulding
Scuffed (Unpainted)
Over 100mm



3: Bumper Front
Hole
UpTo 25mm





4: Bonnet
Scratched
Over 25mm Not Thru Paint




5: Bumper Front Moulding
Scuffed (Unpainted)
Over 100mm


6: Wing nsf
Dented
Over 30% Of Panel



7: Door Mirror Assy nsf
Broken
Replace





8: Door nsr
Dented
Over 30mm





9: Door Moulding nsr
Scuffed (Unpainted)
Over 100mm

10: Qtr Panel nsr
Dented
With Paint Damage





11: Qtr Panel nsr
Scratched
Over 25mm Thru Paint

12: Qtr Panel Trim ns
Scuffed
Over 25mm




13: Sill ns
Dented
With Paint Damage


14: Qtr Panel nsr
Scratched
Over 25mm Thru Paint



15: Qtr Panel Trim ns
Scuffed
Over 25mm





16: Roof
Dented
Over 30mm




17: Door osr
Dented
With Paint Damage


18: Badgedecal Rear
Missing
Replace



19: Qtr Panel osr
Dented
With Paint Damage





20: Qtr Panel osr
Dented
With Paint Damage




21: Qtr Panel osr
Dented
Between 10mm + 30mm


22: Qtr Panel osr
Scratched
Over 25mm Thru Paint



23: Qtr Panel osr
Dented
With Paint Damage





24: Qtr Panel Moulding os
Missing
Replace




25: Qtr Panel osr
Dented
With Paint Damage


26: Qtr Panel Moulding os
Broken
Replace



27: Qtr Panel osr
Dented
With Paint Damage





28: B Post os
Dented
With Paint Damage




29: B Post os
Missing
Replace

30: B Post os
Scratched
Over 25mm Thru Paint



31: Door osf
Dented
Over 30mm



32: Seat Base Cover osf
Holed
Over 3mm

33: Carpets Front
Holed
Over 3mm

Interior

Carpet Condition		Average		Upholstery Condition		Average	
Seat Condition		Average		Odour		No	
Engine Runs		OK		Gearbox 1st and Reverse Test		OK	
Brakes		OK		Clutch Slip Test from Static		OK	
Parking Brake		OK		Gearbox Static Gear Selection (engine running)		OK	
				No Excessive Smoking		OK	

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK