

VEHICLE INSPECTION REPORT

PK67VGR

Daf CF 450

Non Runner
Inspection

Serious Damage?	No	Vehicle	
		VAT	Plus VAT
		V5	Present

Details

Reg. date	09/11/2017	VIN	XLRTGM4100G181303	Cab Type	SLEEPER CAB
Year	2017	Body Style	Tractor Unit	Gearbox	AUTOMATIC
Mileage	963,597 Km Warranted	Service history	Yes	Axle Combi	6x2
Fuel Type	Diesel	Service documents	Printout	Rear Suspension	Air
Colour	RED	MOT Due	30/11/2025		

*NON RUNNER - TURNS OVER WILL NOT START, ENGINE ISSUES**WARNING LIGHT ON DASH*

Tyres



NSF	NSI1	NSI2	NSI3	NSI4
OSF	OSI1	OSI2	OSI3	OSI4
Spare	NSO1	NSO2	NSO3	NSO4
	OSO1	OSO2	OSO3	OSO4

Features

- Radio/CD
- Air conditioning
- Front electric windows
- Central locking
- Cloth seat trim


Photos







Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips



2: Bumper Front
Chipped
Multiple Chips



3: Bumper Front
Dented
Over 30mm



4: Qtr Panel Moulding ns
Broken
Replace



5: Qtr Panel Moulding os
Scuffed (Unpainted)
Over 100mm

Interior

Carpet Condition	OK	Upholstery Condition	OK
Seat Condition	OK	Odour	-
Engine Runs		Fault	